


Instructions for Self-bonding labellings

① Clean surface thoroughly



Clean the surface thoroughly. It must be dry and free of dust and grease. Suitable cleaning agents are glass cleaner or methylated spirits.

② Position the lettering



Position the lettering exactly where you would like to fix it. Mark the right position with tape if needed.

After fixing the lettering, its position cannot be adjusted.

③ Remove the protective foil



Remove the protective foil from the back. When many small pieces of foil are attached, use a needle or a sharp knife.

④ Affix and press the lettering to the surface



Position the lettering carefully according to your markings and press it evenly to the surface. If required, remove the tape.
